

TRACKING EXAMPLE B



DANGEROUS MONITOR ST (OR MONITORING DEVICE)

OUT DAW INTO
MONITOR ST
INPUT 1

OUT MONITOR 1&2 OF
LIAISON INTO MONITOR ST
INPUT 2&4*
(PRE&POST BUSS A)

COMPUTER INTERFACE (DAW/CONVERTER)

OUT BUSS A & B
OF LIAISON
INTO DAW

MIC PREAMP 1

MIC PREAMP 2

OUT PREAMP INTO
BUSS A OF LIAISON

OUT PREAMP INTO
BUSS B OF LIAISON

*Utilizing input 4 on the
MONITOR ST, allows the
post processing level to be
reduced, thus matching it
to the original for true A/B
comparisons.

